

# Air Monitoring Summary Tables

The table below summarizes monitoring data collected using a portable wireless remote monitoring system.

All times in Easter Standard Time (EST).

**From:** 3/15/22 12:00 am

**To:** 3/15/22

11:59 pm

## Offsite Monitors

Instrument	Analyte	ATSDR MRL 14-day Avg Reached?	Concentration Range Detected <sup>a</sup>	24-hr Average <sup>a</sup>	7-day Average	ATSDR 14-day MRL
<b>Catawba Headstart</b>						
Acrulog PPB	H <sub>2</sub> S	No	0 – 1 ppb	0.03 ppb <sup>b</sup>	0.01 ppb	70 ppb
<b>Treetops</b>						
Acrulog PPB	H <sub>2</sub> S	No	0 – 5 ppb	0.33 ppb <sup>c</sup>	0.06 ppb	70 ppb
<b>Liberty Hill</b>						
Acrulog PPB	H <sub>2</sub> S	No	0 – 0 ppb	0.00 ppb <sup>d</sup>	0.00 ppb	70 ppb
<b>Riverchase Estates</b>						
Acrulog PPB	H <sub>2</sub> S	No	0 – 0 ppb	0.00 ppb <sup>e</sup>	0.00 ppb	70 ppb
<b>Millstone Creek</b>						
Acrulog PPB	H <sub>2</sub> S	No	0 – 1 ppb	0.03 ppb	0.00 ppb	70 ppb

<sup>b</sup> Quarterly performance audit at Catawba from 14:00 to 19:00 EST. The 24-hr average at this location is not represented by the full 24-hr period; a total of 11 30-minute averages are missing from the reported period.

<sup>c</sup> Quarterly performance audit at Treetops from 14:30 to 17:30 EST. The 24-hr average at this location is not represented by the full 24-hr period; a total of 7 30-minute averages are missing from the reported period.

<sup>d</sup> Quarterly performance audit at Liberty Hill from 9:30 to 16:30 EST. The 24-hr average at this location is not represented by the full 24-hr period; a total of 15 30-minute averages are missing from the reported period.

<sup>e</sup> Quarterly performance audit at Riverchase Estates from 13:30 to 21:30 EST. The 24-hr average at this location is not represented by the full 24-hr period; a total of 17 30-minute averages are missing from the reported period.

## Onsite Fenceline Monitors

Instrument	Analyte	30-min AEGL Reached?	Concentration Range Detected <sup>a</sup>	24-hr Average <sup>a</sup>	7-day Average	30-min AEGL
<b>Station 1</b>						
TAPI Analyzer	H <sub>2</sub> S	No	0 – 23 ppb	2.30 ppb	1.28 ppb	600 ppb
<b>Station 2</b>						
TAPI Analyzer	H <sub>2</sub> S	No	1 – 7 ppb	1.40 ppb	1.00 ppb	600 ppb
<b>Station 3</b>						
TAPI Analyzer	H <sub>2</sub> S	No	1 – 2 ppb	1.09 ppb <sup>f</sup>	0.83 ppb	600 ppb




<sup>a</sup> Based on 30-minute averages.

<sup>f</sup> Quarterly performance audit at Station 3 from 9:00 to 12:00 EST. The 24-hr average at this location is not represented by the full 24-hr period; a total of 7 30-minute averages are missing from the reported period.

### Notes:

ATSDR MRL	Agency for Toxic Substances and Disease Registry Minimal Risk Level (MRL)
AEGL	EPA Acute Exposure Guidelines Levels
H <sub>2</sub> S	Hydrogen Sulfide
TAPI	Teledyne API H <sub>2</sub> S Analyzer
hr	Hour
min	Minute
ppb	Parts per billion
MRL Limit	Limit defined as a 14-day average value.

Wind rose – Shows the direction the wind is coming from, the monitoring station being at the center of the rose.




## Period H<sub>2</sub>S Monitoring Hydrogen Sulfide Offsite Monitors

Below are graphs for offsite locations where hydrogen sulfide (H<sub>2</sub>S) was detected during the current reporting period.


The five stand-alone H<sub>2</sub>S monitoring stations correlate with five previous EPA's Viper monitoring system which includes areas to the north-northeast and south-southwest of the New-Indy Catawba Mill.

Winds came from the south - southwest at 1 to 4 miles per hour.


See wind rose diagram with aerial map figure for full wind data during this reporting period.




### Treetops - 3/15/2022




### Liberty Hill - 3/15/2022



### Riverchase Estates - 3/15/2022



### Millstone Creek - 3/15/2022



## Period H<sub>2</sub>S Monitoring



### Hydrogen Sulfide Onsite Monitors

Below are graphs for onsite locations during the current reporting period.

Depending on wind direction, the H<sub>2</sub>S measured at the onsite fence line locations may not exit mill property at reported concentrations. Wind directions from offsite locations, blowing onto mill property, will disperse ambient concentrations to lower levels prior to exiting the plant site.

Winds came from the south - southwest at 1 to 4 miles per hour.

See wind rose diagram with aerial map figure for full wind data during this reporting period.



### Station3 - 3/15/2022

